

Menu

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

Print

[Save](#)

Email

[Resource detail](#)

[Citations](#)

## Repairing earthquake damaged wall linings - Build 126(2011)

[View on Information Provider website](#) [Download this resource \(PDF, 1.5MB\)](#)

{{ linkText }}

### Abbreviation

Repairing earthquake damaged wall linings

### Valid from

01/10/2011

---

### Information provider

BRANZ Limited

### Information type

BUILD article

### Format

Website, PDF

---

### Description

Many Canterbury houses have lost stiffness and strength following the earthquakes. Repairs to gypsum plasterboard linings need to restore this to prevent future small events repeating the cracking and damage.

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#) [Download this resource \(PDF, 1.5MB\)](#)

{{ linkText }}

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

# Repairing earthquake damaged wall linings - Build 126(2011)

This document is not CITED BY any other resources:

Back

# Repairing earthquake damaged wall linings - Build 126(2011)

Show what documents this resource is CITED BY

Show what documents this resource CITES

## Description

Many Canterbury houses have lost stiffness and strength following the earthquakes. Repairs to gypsum plasterboard linings need to restore this to prevent future small events repeating the cracking and damage.

[View on Information Provider website](#) [Download this resource \(PDF, 1.5MB\)](#)

[Repairing earthquake damaged wall linings - Build 126\(2011\)](#)

## Description

Many Canterbury houses have lost stiffness and strength following the earthquakes. Repairs to gypsum plasterboard linings need to restore this to prevent future small events repeating the cracking and damage.

[View on Information Provider website](#) [Download this resource \(PDF, 1.5MB\)](#)

This resource does not cite any other resources.

# Repairing earthquake damaged wall linings - Build 126(2011)

This resource does not CITE any other resources.

Back

Close

## Table of Contents

Print [Save](#) Email

[Feedback](#)

--	--	--

--

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

--	--	--

--

[Feedback](#)