

Menu

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

Print

[Save](#)

Email

[Resource detail](#)

[Citations](#)

Warning 2018/001 - Warning about the use of loop bar details in flange-hung double-tee precast concrete floor units.

[View on Information Provider website](#) [Download this resource \(PDF, 227KB\)](#)

{{ linkText }}

Abbreviation

Warning 2018/001

Valid from

03/04/2018

Information provider

Ministry of Business, Innovation and Employment

Author

Ministry of Business, Innovation and Employment

Information type

Section 26 warning/ban

Format

PDF

Description

The Chief Executive of the Ministry of Business, Innovation and Employment (MBIE) is warning that the use of loop bar details in flange-hung double-tee precast concrete floor units that do not comply with NZS 3101.1:2006 Amendment 3 is likely to fail to comply with clause B1 Structure of the New Zealand Building Code.

This warning came into force on 3 April 2018 and will remain in place until amended or revoked by MBIE.

Scope

The warning applies to all building consent applications for new building work. It does not apply to existing buildings.

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#) [Download this resource \(PDF, 227KB\)](#)

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

Warning 2018/001 - Warning about the use of loop bar details in flange-hung double-tee precast concrete floor units.

This document is not CITED BY any other resources:

Warning 2018/001 - Warning about the use of loop bar details in flange-hung double-tee precast concrete floor units.

Description

The Chief Executive of the Ministry of Business, Innovation and Employment (MBIE) is warning that the use of loop bar details in flange-hung double-tee precast concrete floor units that do not comply with NZS 3101.1:2006 Amendment 3 is likely to fail to comply with clause B1 Structure of the New Zealand Building Code.

This warning came into force on 3 April 2018 and will remain in place until amended or revoked by MBIE.

[View on Information Provider website](#) [Download this resource \(PDF, 227KB\)](#)

[Warning 2018/001 - Warning about the use of loop bar details in flange-hung double-tee precast concrete floor units.](#)

Description

The Chief Executive of the Ministry of Business, Innovation and Employment (MBIE) is warning that the use of loop bar details in flange-hung double-tee precast concrete floor units that do not comply with NZS 3101.1:2006 Amendment 3 is likely to fail to comply with clause B1 Structure of the New

Zealand Building Code.

This warning came into force on 3 April 2018 and will remain in place until amended or revoked by MBIE.

[View on Information Provider website](#) [Download this resource \(PDF, 227KB\)](#)

This resource does not cite any other resources.

Warning 2018/001 - Warning about the use of loop bar details in flange-hung double-tee precast concrete floor units.

This resource does not CITE any other resources.

Back

Close

Table of Contents

Print [Save](#) Email

[Feedback](#)

<input type="text"/>	<input type="text"/>	<input type="text"/>
----------------------	----------------------	----------------------

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

<input type="text"/>	<input type="text"/>	<input type="text"/>
----------------------	----------------------	----------------------

[Feedback](#)