

Menu

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

Print

[Save](#)

Email

[Resource detail](#)

[Citations](#)

## 2003/07: Weathertightness of an infill wall-column junction

[View on Information Provider website](#) [Download this resource \(PDF, 0KB\)](#)

Abbreviation

2003/07

Valid from

23/04/2003

---

Information provider

Ministry of Business, Innovation and Employment

Information type

Determination

Format

PDF

---

**Description**

The matter for determination is the weathertightness of the junction between an infill wall and a structural column, and whether the junction as installed is such that the exterior wall complies with clause E2.3.2 of the building code.

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#) [Download this resource \(PDF, 0KB\)](#)

For assistance with locating previous versions, please contact the information provider.

**This resource is not cited by any other resources.**

# 2003/07: Weathertightness of an infill wall-column junction

This document is not CITED BY any other resources:

Back

# 2003/07: Weathertightness of an infill wall-column junction

Show what documents this resource is CITED BY

Show what documents this resource CITES

## Description

The matter for determination is the weathertightness of the junction between an infill wall and a structural column, and whether the junction as installed is such that the exterior wall complies with clause E2.3.2 of the building code.

[View on Information Provider website](#) [Download this resource \(PDF, 0KB\)](#)

[2003/07: Weathertightness of an infill wall-column junction](#)

## Description

The matter for determination is the weathertightness of the junction between an infill wall and a structural column, and whether the junction as installed is such that the exterior wall complies with clause E2.3.2 of the building code.

[View on Information Provider website](#) [Download this resource \(PDF, 0KB\)](#)

This resource does not cite any other resources.

# 2003/07: Weathertightness of an infill wall-column junction

This resource does not CITE any other resources.

Back

Close

## Table of Contents

Print [Save](#) Email

[Feedback](#)

--	--	--

--

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

--	--	--

--

[Feedback](#)