

Menu

- [Home](#)
- [About this portal](#)
- [Latest updates](#)

Print

[Save](#)

Email

[Resource detail](#)

[Citations](#)

2006/025: Issue of a notice to fix requiring conservatory spouting connection to an approved outlet

[View on Information Provider website](#) [Download this resource \(PDF, 0KB\)](#)

Abbreviation

2006/025

Valid from

03/04/2006

Information provider

Ministry of Business, Innovation and Employment

Information type

Determination

Format

PDF

Description

The dispute to be determined was whether the down-pipe from the conservatory spouting should be connected to an approved storm water disposal system as required in a notice to fix.

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#) [Download this resource \(PDF, 0KB\)](#)

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

2006/025: Issue of a notice to fix requiring conservatory spouting connection to an approved outlet

This document is not CITED BY any other resources:

Back

2006/025: Issue of a notice to fix requiring conservatory spouting connection to an approved outlet

Show what documents this resource is CITED BY

Show what documents this resource CITES

Description

The dispute to be determined was whether the down-pipe from the conservatory spouting should be connected to an approved storm water disposal system as required in a notice to fix.

[View on Information Provider website](#) [Download this resource \(PDF, 0KB\)](#)

[2006/025: Issue of a notice to fix requiring conservatory spouting connection to an approved outlet](#)

Description

The dispute to be determined was whether the down-pipe from the conservatory spouting should be connected to an approved storm water disposal system as required in a notice to fix.

[View on Information Provider website](#) [Download this resource \(PDF, 0KB\)](#)

This resource does not cite any other resources.

2006/025: Issue of a notice to fix requiring conservatory spouting connection to an approved outlet

This resource does not CITE any other resources.

Back

Close

Table of Contents

Print

[Save](#)

Email

[Feedback](#)

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

[Feedback](#)