Skip to main content Skip to primary navigation	
Menu	
Home Home	
About this portal	
Latest updates	
<u></u>	
Print Save Email	
Resource detail	
Citations	

2011/032: Refusal to issue a code compliance certificate for an 8 year-old house

<u>View on Information Provider website Download this resource (PDF, 260KB)</u> {{ linkText }}

Abbreviation 2011/032 Valid from 13/04/2011 Information provider Ministry of Business, Innovation and Employment Information type Determination Format PDF

Description

This determination arises from the decision of the authority to refuse to issue a code compliance certificate for an 8-year-old house, because it is not satisfied that the building work complies with the Building Code. The refusal arose because the authority has concerns about: the adequacy of inspections undertaken during construction; the compliance of the house with certain clausesof the Building Code, relating to weathertightness of the building envelope and the adequacy of the structural elements; and the durability of the building work as it was substantially completed in 2003. The matter to be determined is therefore whether the authority was correct to refuse to issue a code compliance certificate. In deciding this, the following must be considered: 1-Whether the external building envelope of the house complies with Clause B2 Durability and Clause E2 External Moisture of the Building Code. The building envelope includes the components of the systems (such as the plywood cladding, the profiled metal cladding, the concrete block walls, the windows, the decks, the roof cladding and the flashings), as well as the way the components have been installed and work together; 2-Whether the house complies with Clause B1 Structure of the Building Code, taking into account the level of oversight provided by the engineers and the authority during construction; 3-Whether the building elements comply with Clause B2 Durability of the building Code, taking into account the level of oversight provided by the engineers and the authority during construction; 3-Whether the building elements comply with Clause B2 Durability of the building Code, taking into account the level of oversight provided by the engineers and the authority during construction; 3-

For assistance with locating previous versions, please contact the information provider.

<u>View on Information Provider website Download this resource (PDF, 260KB)</u> {{ linkText }}

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

2011/032: Refusal to issue a code compliance certificate for an 8 year-old house

Back

2011/032: Refusal to issue a code compliance certificate for an 8 year-old house

Show what documents this resource is CITED BY

Show what documents this resource CITES

Description

This determination arises from the decision of the authority to refuse to issue a code compliance certificate for an 8-year-old house, because it is not satisfied that the building work complies with the Building Code. The refusal arose because the authority has concerns about: the adequacy of inspections undertaken during construction; the compliance of the house with certain clausesof the Building Code, relating to weathertightness of the building envelope and the adequacy of the structural elements; and the durability of the building work as it was substantially completed in 2003. The matter to be determined is therefore whether the authority was correct to refuse to issue a code compliance certificate. In deciding this, the following must be considered: 1-Whether the external building envelope of the house complies with Clause B2 Durability and Clause E2 External Moisture of the Building Code. The building envelope includes the components of the systems (such as the plywood cladding, the profiled metal cladding, the concrete block walls, the windows, the decks, the roof cladding and the flashings), as well as the way the components have been installed and work together; 2-Whether the house complies with Clause B1 Structure of the Building Code, taking into account the level of oversight provided by the engineers and the authority during construction; 3-Whether the building elements comply with Clause B2 Durability of the building Code, taking into account the level of the building of the Building Code, taking into account the house.

View on Information Provider website Download this resource (PDF, 260KB)

2011/032: Refusal to issue a code compliance certificate for an 8 year-old house

Description

This determination arises from the decision of the authority to refuse to issue a code compliance certificate for an 8-year-old house, because it is not satisfied that the building work complies with the Building Code. The refusal arose because the authority has concerns about: the adequacy of inspections undertaken during construction; the compliance of the house with certain clausesof the Building Code, relating to weathertightness of the building envelope and the adequacy of the structural elements; and the durability of the building work as it was substantially completed in 2003. The matter to be determined is therefore whether the authority was correct to refuse to issue a code compliance certificate. In deciding this, the following must be considered: 1-Whether the external building envelope of the house complies with Clause B2 Durability and Clause E2 External Moisture of the Building Code. The building envelope includes the components of the systems (such as the plywood cladding, the profiled metal cladding, the concrete block walls, the windows, the decks, the roof cladding and the flashings), as well as the way the components have been installed and work together; 2-Whether the house complies with Clause B1 Structure of the Building Code, taking into account the level of oversight provided by the engineers and the authority during construction; 3-Whether the building elements comply with Clause B2 Durability of the building code, taking into account the level of oversight provided by the Building Code, taking into account the age of the house.

View on Information Provider website Download this resource (PDF, 260KB)


This resource does not cite any other resources.

2011/032: Refusal to issue a code compliance certificate for an 8 year-old house

This resource does not CITE any other resources.

Back	
Close	

Table of Contents



Feedback