

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

  
  

[Save](#)

[Resource detail](#)

[Citations](#)

## 2013/069: Regarding the refusal to issue a code compliance certificate for a new medical centre because of the height of the door handles.

[View on Information Provider website](#) [Download this resource \(PDF, 99KB\)](#)

Abbreviation

2013/069

Valid from

11/11/2013

---

Information provider

Ministry of Business, Innovation and Employment

Information type

Determination

Format

PDF

---

### Description

The application for this determination arose from the construction of a new medical centre with door handles set at 1400mm above floor level.

The authority was of the view that the door handles did not comply with Clause D1 of the Building Code and accordingly refused to issue the code compliance certificate.

The matter to be determined was therefore whether the authority was correct to refuse to issue the code compliance certificate.

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#) [Download this resource \(PDF, 99KB\)](#) {{ linkText }}

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

## **2013/069: Regarding the refusal to issue a code compliance certificate for a new medical centre because of the height of the door handles.**

This document is not CITED BY any other resources:

[Back](#)

## **2013/069: Regarding the refusal to issue a code compliance certificate for a new medical centre because of the height of the door handles.**

[Show what documents this resource is CITED BY](#)

[Show what documents this resource CITES](#)

### **Description**

The application for this determination arose from the construction of a new medical centre with door handles set at 1400mm above floor level.

The authority was of the view that the door handles did not comply with Clause D1 of the Building Code and accordingly refused to issue the code compliance certificate.

The matter to be determined was therefore whether the authority was correct to refuse to issue the code compliance certificate.

[View on Information Provider website](#) [Download this resource \(PDF, 99KB\)](#)

[2013/069: Regarding the refusal to issue a code compliance certificate for a new medical centre because of the height of the door handles.](#)

### **Description**

The application for this determination arose from the construction of a new medical centre with door handles set at 1400mm above floor level.

The authority was of the view that the door handles did not comply with Clause D1 of the Building Code and accordingly refused to issue the code compliance certificate.

The matter to be determined was therefore whether the authority was correct to refuse to issue the code compliance certificate.

[View on Information Provider website](#) [Download this resource \(PDF, 99KB\)](#)

This resource does not cite any other resources.

## 2013/069: Regarding the refusal to issue a code compliance certificate for a new medical centre because of the height of the door handles.

This resource does not CITE any other resources.

Back

Close

### Table of Contents

Print

[Save](#)

Email

[Feedback](#)

<input type="text"/>	<input type="text"/>	<input type="text"/>
----------------------	----------------------	----------------------

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

<input type="text"/>	<input type="text"/>	<input type="text"/>
----------------------	----------------------	----------------------

[Feedback](#)