

Menu

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

Print

[Save](#)

Email

[Resource detail](#)

[Citations](#)

2017/081: Compliance of ground floor stairs landing in residential unit

[View on Information Provider website](#) [Download this resource \(PDF, 361KB\)](#)

{{ linkText }}

Abbreviation

2017/081

Valid from

20/11/2017

Information provider

Ministry of Business, Innovation and Employment

Author

Ministry of Business, Innovation and Employment

Information type

Determination

Format

PDF

Description

This determination considered the compliance of a 435mm long landing at the bottom of a set of internal stairs.

The determination compared the landing length with the Acceptable Solution and discussed whether there was adequate activity space between the door and the stairs.

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#) [Download this resource \(PDF, 361KB\)](#)

{{ linkText }}

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

2017/081: Compliance of ground floor stairs landing in residential unit

This document is not CITED BY any other resources:

Back

2017/081: Compliance of ground floor stairs landing in residential unit

Show what documents this resource is CITED BY

Show what documents this resource CITES

Description

This determination considered the compliance of a 435mm long landing at the bottom of a set of internal stairs.

The determination compared the landing length with the Acceptable Solution and discussed whether there was adequate activity space between the door and the stairs.

[View on Information Provider website](#) [Download this resource \(PDF, 361KB\)](#)

[2017/081: Compliance of ground floor stairs landing in residential unit](#)

Description

This determination considered the compliance of a 435mm long landing at the bottom of a set of internal stairs.

The determination compared the landing length with the Acceptable Solution and discussed whether there was adequate activity space between the door and the stairs.

[View on Information Provider website](#) [Download this resource \(PDF, 361KB\)](#)

This resource does not cite any other resources.

2017/081: Compliance of ground floor stairs landing in residential unit

This resource does not CITE any other resources.

Back

Close

Table of Contents

Print [Save](#) Email

[Feedback](#)

--	--	--

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

--	--	--

[Feedback](#)