

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

[Save](#)

[Resource detail](#)
[Citations](#)

2019/039: Regarding the exposure zone for building work located near a tidal estuary

[View on Information Provider website](#) [Download this resource \(PDF, 302KB\)](#)

Abbreviation

2019/039

Valid from

19/08/2019

Information provider

Ministry of Business, Innovation and Employment

Information type

Determination

Format

PDF

Description

This determination considers what is the appropriate exposure zone for a house located near a tidal estuary and the protection that is required to the brick ties used to secure the brick cladding.

The authority considered that the house was located in exposure Zone D which required stainless steel ties to be used.

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#) [Download this resource \(PDF, 302KB\)](#)

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

2019/039: Regarding the exposure zone for building work located near a tidal estuary

This document is not CITED BY any other resources:

2019/039: Regarding the exposure zone for building work located near a tidal estuary

Show what documents this resource is CITED BY

Show what documents this resource CITES

Description

This determination considers what is the appropriate exposure zone for a house located near a tidal estuary and the protection that is required to the brick ties used to secure the brick cladding.

The authority considered that the house was located in exposure Zone D which required stainless steel ties to be used.

[View on Information Provider website](#) [Download this resource \(PDF, 302KB\)](#)

[2019/039: Regarding the exposure zone for building work located near a tidal estuary](#)

Description

This determination considers what is the appropriate exposure zone for a house located near a tidal estuary and the protection that is required to the brick ties used to secure the brick cladding.

The authority considered that the house was located in exposure Zone D which required stainless steel ties to be used.

[View on Information Provider website](#) [Download this resource \(PDF, 302KB\)](#)

This resource does not cite any other resources.

2019/039: Regarding the exposure zone for building work located near a tidal estuary

This resource does not CITE any other resources.

Back

Close

Table of Contents

Print

[Save](#)

Email

[Feedback](#)

| | | |
|----------------------|----------------------|----------------------|
| <input type="text"/> | | |
| <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | | |

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

| | | |
|----------------------|----------------------|----------------------|
| <input type="text"/> | <input type="text"/> | <input type="text"/> |
| <input type="text"/> | | |

[Feedback](#)