

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

[Save](#)

[Resource detail](#)
[Citations](#)

AS 1462.11-1990 Methods of test for unplasticized PVC (UPVC) pipes and fittings - Method 11: Method for high temperature stress-relief testing of UPVC fittings

[View on Information Provider website](#)

Abbreviation

AS 1462.11-1990

Valid from

01/01/1990

Information provider

SAI Global

Author

Standards Australia

Information type

Australian Standard

Format

Hard copy

Cited By

[This resource is cited by 1 document \(show Citations\)](#)

Description

This Standard describes the method for high temperature stress-relief testing of UPVC fittings.

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#)

For assistance with locating previous versions, please contact the information provider.

This resource is cited by:

AS 1462.11-1990 Methods of test for unplasticized PVC (UPVC) pipes and fittings - Method 11: Method for high temperature stress-relief testing of UPVC fittings

This document is CITED BY:

- [AS 1273-1991](#)

AS 1462.11-1990 is cited by AS 1273-1991 (R2018) Unplasticized PVC (UPVC) downpipe and fittings for rainwater

[Back](#)

AS 1462.11-1990 Methods of test for unplasticized PVC (UPVC) pipes and fittings - Method 11: Method for high temperature stress-relief testing of UPVC fittings

Show what documents this resource is CITED BY

Show what documents this resource CITES

Description

This Standard describes the method for high temperature stress-relief testing of UPVC fittings.

[View on Information Provider website](#)

[AS 1462.11-1990 Methods of test for unplasticized PVC \(UPVC\) pipes and fittings - Method 11: Method for high temperature stress-relief testing of UPVC fittings](#)

Description

This Standard describes the method for high temperature stress-relief testing of UPVC fittings.

[View on Information Provider website](#)

This resource does not cite any other resources.

AS 1462.11-1990 Methods of test for unplasticized PVC (UPVC) pipes and fittings - Method 11: Method for high temperature stress-relief testing of UPVC fittings

This resource does not CITE any other resources.

[Back](#)

[Close](#)

Table of Contents

[Print](#) [Save](#) [Email](#)

[Feedback](#)

<input type="text"/>		
<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>		

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>		

[Feedback](#)