

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

[Resource detail](#)
[Citations](#)

AS 3706.11-1990 Geotextiles - Methods of test - Method 11: Determination of durability - Resistance to degradation by light and heat

[View on Information Provider website](#)

Abbreviation

AS 3706.11-1990

Valid from

15/10/1990

Information provider

SAI Global

Author

Standards Australia

Information type

Australian Standard

Format

PDF

Cited By

[This resource is cited by 1 document \(show Citations\)](#)

Description

The Standard sets out a method for determining the durability of geotextiles when subjected to degradation by artificial light and heat.

Notes:

1. As the artificial light source produces heat, it is expedient to combine the tests for these two agencies of degradation.
2. Two testing periods are given, referred to as the standard period and the extended period, so that the effects of additional exposure can be assessed if required.
3. Materials with poor stability to light will usually show considerable loss of strength after the standard period of exposure.

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#)

For assistance with locating previous versions, please contact the information provider.

This resource is cited by:

AS 3706.11-1990 Geotextiles - Methods of test - Method 11: Determination of

durability - Resistance to degradation by light and heat

This document is CITED BY:

- [AS 3706.1-2003](#)

AS 3706.11-1990 is cited by AS 3706.1-2003 Geotextiles - Methods of test. Part 1: General requirements, sampling, conditioning, basic physical properties and statistical analysis

Back

AS 3706.11-1990 Geotextiles - Methods of test - Method 11: Determination of durability - Resistance to degradation by light and heat

Show what documents this resource is CITED BY

Show what documents this resource CITES

Description

The Standard sets out a method for determining the durability of geotextiles when subjected to degradation by artificial light and heat.

Notes:

1. As the artificial light source produces heat, it is expedient to combine the tests for these two agencies of degradation.
2. Two testing periods are given, referred to as the standard period and the extended period, so that the effects of additional exposure can be assessed if required.
3. Materials with poor stability to light will usually show considerable loss of strength after the standard period of exposure.

[View on Information Provider website](#)

[AS 3706.11-1990 Geotextiles - Methods of test - Method 11: Determination of durability - Resistance to degradation by light and heat](#)

Description

The Standard sets out a method for determining the durability of geotextiles when subjected to degradation by artificial light and heat.

Notes:

1. As the artificial light source produces heat, it is expedient to combine the tests for these two agencies of degradation.
2. Two testing periods are given, referred to as the standard period and the extended period, so that the effects of additional exposure can be assessed if required.
3. Materials with poor stability to light will usually show considerable loss of strength after the standard period of exposure.

[View on Information Provider website](#)

This resource does not cite any other resources.

AS 3706.11-1990 Geotextiles - Methods of test - Method 11: Determination of durability - Resistance to degradation by light and heat

This resource does not CITE any other resources.

Back

Close

Table of Contents

Print Save Email

[Feedback](#)

| | | |
|--|--|--|
| | | |
| | | |
| | | |

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

| | | |
|--|--|--|
| | | |
| | | |

[Feedback](#)