| Skip to main content Skip to primary navigation Menu Menu |
|---|
| <u>Home Home</u> <u>About this portal</u> <u>Latest updates</u> |
| |
| Print Save Email Resource detail Citations |
| Brick veneer over habitable spaces - Build 121(2010) |
| View on Information Provider website Download this resource (PDF, 1.4MB) {{ linkText }} |

Abbreviation Brick veneer over habitable spaces Valid from 01/12/2010

Information provider BRANZ Limited Information type BUILD article Format Website, PDF

Description

Some external moisture is likely to penetrate masonry veneer, but this isnt a problem when sufficient ventilation can drain and dry any water that enters. In this example, poor construction details restricted ventilation and caused problems.

For assistance with locating previous versions, please contact the information provider.

| View on Information Provider website Download this resource (PDF, 1.4MB) | }} | linkText } } | l |
|--|----|--------------|---|
| | | | |

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

Brick veneer over habitable spaces - Build 121(2010)

This document is not CITED BY any other resources:



Brick veneer over habitable spaces - Build 121(2010)

Show what documents this resource is CITED BY Show what documents this resource CITES

Description

Some external moisture is likely to penetrate masonry veneer, but this isnt a problem when sufficient ventilation can drain and

dry any water that enters. In this example, poor construction details restricted ventilation and caused problems.

View on Information Provider website Download this resource (PDF, 1.4MB)

Brick veneer over habitable spaces - Build 121(2010)

Description

Some external moisture is likely to penetrate masonry veneer, but this isnt a problem when sufficient ventilation can drain and dry any water that enters. In this example, poor construction details restricted ventilation and caused problems.

View on Information Provider website Download this resource (PDF, 1.4MB)

This resource does not cite any other resources.

Brick veneer over habitable spaces - Build 121(2010)

This resource does not CITE any other resources.

Back

Close

Table of Contents



- <u>Contact us</u>
- Privacy policy
- **Disclaimer**
- <u>Copyright</u>



Feedback