

Menu

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

Print

[Save](#)

Email

[Resource detail](#)

[Citations](#)

Concrete masonry and weathertightness

[View on Information Provider website](#)

{{ linkText }}

Valid from

01/04/2010

Information provider

Ministry of Business, Innovation and Employment

Information type

Section 175 guidance

Format

Website

Description

The Acceptable Solution for weathertightness E2/AS1 is a solution for claddings on timber frame structures and is not applicable to other nonframed structural systems such as concrete masonry.

NZS 4229 does offer some guidance as to surface coatings that have been considered adequate by a Standards committee, but these nevertheless remain as alternative solutions, and outside the Acceptable Solutions and Verification Methods for automatic acceptance by BCAs.

Scope

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#)

{{ linkText }}

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

Concrete masonry and weathertightness

This document is not CITED BY any other resources:

Back

Concrete masonry and weathertightness

Show what documents this resource is CITED BY

Show what documents this resource CITES

Description

The Acceptable Solution for weathertightness E2/AS1 is a solution for claddings on timber frame structures and is not applicable to other nonframed structural systems such as concrete masonry.

NZS 4229 does offer some guidance as to surface coatings that have been considered adequate by a Standards committee, but these nevertheless remain as alternative solutions, and outside the Acceptable Solutions and Verification Methods for automatic acceptance by BCAs.

[View on Information Provider website](#)

[Concrete masonry and weathertightness](#)

Description

The Acceptable Solution for weathertightness E2/AS1 is a solution for claddings on timber frame structures and is not applicable to other nonframed structural systems such as concrete masonry.

NZS 4229 does offer some guidance as to surface coatings that have been considered adequate by a Standards committee, but these nevertheless remain as alternative solutions, and outside the Acceptable Solutions and Verification Methods for automatic acceptance by BCAs.

[View on Information Provider website](#)

This resource does not cite any other resources.

Concrete masonry and weathertightness

This resource does not CITE any other resources.

Back

Close

Table of Contents

Print

[Save](#)

Email

[Feedback](#)

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

[Feedback](#)