Skip to main content Skip to primary navigation Menu	
 Home Home About this portal Latest updates	
Print Save Email Resource detail Citations	
Introduction to repairing and	•

Introduction to repairing and rebuilding houses affected by the Canterbury earthquakes - Part C: Assessing, repairing and rebuilding foundations in TC3

<u>View on Information Provider website Download this resource (PDF, 2.6MB)</u> {{ linkText }}

Version

3a

Valid from

01/12/2012

Information provider

Ministry of Business, Innovation and Employment

Information type

Section 175 guidance

Format

PDF

Description

The guidance provided in Part C focuses on foundation repairs and reconstruction for houses in Foundation Technical Category 3 (TC3) areas within the Green Zone of the earthquake-affected parts of the Canterbury region. It does not apply to the Residential Red Zone where significantly poorer ground conditions exist and more severe land damage is expected in future earthquakes.

Previous versions:

For assistance with locating previous versions, please contact the information provider.

<u>View on Information Provider website Download this resource (PDF, 2.6MB)</u> {{ linkText }}

Previous versions

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

Introduction to repairing and rebuilding houses affected by the Canterbury earthquakes - Part C: Assessing, repairing and rebuilding foundations in TC3

This document is not CITED BY any other resources:

Back

Introduction to repairing and rebuilding houses affected by the Canterbury earthquakes - Part C: Assessing, repairing and rebuilding foundations in TC3

Show what documents this resource is CITED BY

Show what documents this resource CITES

Description

The guidance provided in Part C focuses on foundation repairs and reconstruction for houses in Foundation Technical Category 3 (TC3) areas within the Green Zone of the earthquake-affected parts of the Canterbury region. It does not apply to the Residential Red Zone where significantly poorer ground conditions exist and more severe land damage is expected in future earthquakes.

View on Information Provider website Download this resource (PDF, 2.6MB)

Introduction to repairing and rebuilding houses affected by the Canterbury earthquakes - Part C: Assessing, repairing and rebuilding foundations in TC3

Description

The guidance provided in Part C focuses on foundation repairs and reconstruction for houses in Foundation Technical Category 3 (TC3) areas within the Green Zone of the earthquake-affected parts of the Canterbury region. It does not apply to the Residential Red Zone where significantly poorer ground conditions exist and more severe land damage is expected in future earthquakes.

View on Information Provider website Download this resource (PDF, 2.6MB)

This resource does not cite any other resources.

Introduction to repairing and rebuilding houses affected by the Canterbury earthquakes - Part C: Assessing, repairing and rebuilding foundations in TC3

This resource does not CITE any other resources.
Back Close
Table of Contents
Print Save Email Feedback
 Contact us Privacy policy Disclaimer Copyright
Feedback