

Menu

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

Print

[Save](#)

Email

[Resource detail](#)

[Citations](#)

Veranda rafter fixings - Build 165(2018)

[Download this resource \(PDF\)](#)

Abbreviation

Veranda rafter fixings

Valid from

01/04/2018

Information provider

BRANZ Limited

Information type

BUILD article

Format

PDF

Description

The BRANZ helpline often gets asked about fixings for veranda rafters. These are not covered in NZS 3604:2011, but BRANZ has some advice.

FIXINGS FOR ORDINARY RAFTERS are covered in NZS 3604:2011 *Timber-framed buildings*, as are veranda beams and posts.

Veranda rafters generally span between a ribbon plate attached to the wall of the building and a veranda beam and may overhang the veranda beam by up to 750 mm depending on the size of the rafter. Wind uplift loading under such veranda overhangs is higher than for ordinary rafters so the rafter fixings in NZS 3604:2011 Table 10.1 may not be adequate for some situations.

[Download this resource \(PDF\)](#)

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

Veranda rafter fixings - Build 165(2018)

This document is not CITED BY any other resources:

Veranda rafter fixings - Build 165(2018)

Description

The BRANZ helpline often gets asked about fixings for veranda rafters. These are not covered in NZS 3604:2011, but BRANZ has some advice.

FIXINGS FOR ORDINARY RAFTERS are covered in NZS 3604:2011 *Timber-framed buildings*, as are veranda beams and posts.

Veranda rafters generally span between a ribbon plate attached to the wall of the building and a veranda beam and may overhang the veranda beam by up to 750 mm depending on the size of the rafter. Wind uplift loading under such veranda overhangs is higher than for ordinary rafters so the rafter fixings in NZS 3604:2011 Table 10.1 may not be adequate for some situations.

[Download this resource \(PDF\)](#)

[Veranda rafter fixings - Build 165\(2018\)](#)

Description

The BRANZ helpline often gets asked about fixings for veranda rafters. These are not covered in NZS 3604:2011, but BRANZ has some advice.

FIXINGS FOR ORDINARY RAFTERS are covered in NZS 3604:2011 *Timber-framed buildings*, as are veranda beams and posts.

Veranda rafters generally span between a ribbon plate attached to the wall of the building and a veranda beam and may overhang the veranda beam by up to 750 mm depending on the size of the

rafter. Wind uplift loading under such veranda overhangs is higher than for ordinary rafters so the rafter fixings in NZS 3604:2011 Table 10.1 may not be adequate for some situations.

[Download this resource \(PDF\)](#)

This resource does not cite any other resources.

Veranda rafter fixings - Build 165(2018)

This resource does not CITE any other resources.

Back

Close

Table of Contents

Print [Save](#) Email

[Feedback](#)

<input type="text"/>	<input type="text"/>	<input type="text"/>
----------------------	----------------------	----------------------

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

<input type="text"/>	<input type="text"/>	<input type="text"/>
----------------------	----------------------	----------------------

[Feedback](#)