

Menu

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

Print

[Save](#)

Email

[Resource detail](#)

[Citations](#)

## 2007/102: Determination regarding the refusal of a code compliance certificate for a house

[View on Information Provider website](#) [Download this resource \(PDF, 175KB\)](#)

{{ linkText }}

Abbreviation

2007/102

Valid from

06/09/2007

---

Information provider

Ministry of Business, Innovation and Employment

Information type

Determination

Format

PDF

---

### Description

The matter for determination was whether the territorial authority's decision to decline to issue a code compliance certificate for the 1-year-old house was correct.

The refusal arose because the territorial authority considered that the weatherproofing at the cladding corners and the external joinery unit perimeters as detailed in the approved building consent documents and as-built did not meet the requirements of the Compliance Document E2/AS1.

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#) [Download this resource \(PDF, 175KB\)](#)

{{ linkText }}

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

## **2007/102: Determination regarding the refusal of a code compliance certificate for a house**

This document is not CITED BY any other resources:

Back

## **2007/102: Determination regarding the refusal of a code compliance certificate for a house**

Show what documents this resource is CITED BY

Show what documents this resource CITES

### **Description**

The matter for determination was whether the territorial authority's decision to decline to issue a code compliance certificate for the 1-year-old house was correct.

The refusal arose because the territorial authority considered that the weatherproofing at the cladding corners and the external joinery unit perimeters as detailed in the approved building consent documents and as-built did not meet the requirements of the Compliance Document E2/AS1.

[View on Information Provider website](#) [Download this resource \(PDF, 175KB\)](#)

[2007/102: Determination regarding the refusal of a code compliance certificate for a house](#)

### **Description**

The matter for determination was whether the territorial authority's decision to decline to issue a code compliance certificate for the 1-year-old house was correct.

The refusal arose because the territorial authority considered that the weatherproofing at the cladding corners and the external joinery unit perimeters as detailed in the approved building consent documents and as-built did not meet the requirements of the Compliance Document E2/AS1.

[View on Information Provider website](#) [Download this resource \(PDF, 175KB\)](#)

This resource does not cite any other resources.

# 2007/102: Determination regarding the refusal of a code compliance certificate for a house

This resource does not CITE any other resources.

Back

Close

## Table of Contents

Print

[Save](#)

Email

[Feedback](#)

--	--	--

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

--	--	--

[Feedback](#)