

Menu

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

Print

[Save](#)

Email

[Resource detail](#)

[Citations](#)

2008/024: Refusal to issue a code compliance certificate for a new house due to a dispute over compliance of jamb flashing

[View on Information Provider website](#) [Download this resource \(PDF, 87KB\)](#)

{{ linkText }}

Abbreviation

2008/024

Valid from

17/04/2008

Information provider

Ministry of Business, Innovation and Employment

Information type

Determination

Format

PDF

Description

This determination arises from the decision of the territorial authority to refuse to issue a code compliance certificate for a new house because it was not satisfied that it complied with Clauses B2 'Durability' and E2 'External Moisture of the Building Code. The matter for determination is whether the jamb flashing system to the exterior joinery units as installed to the walls of the building comply with Clauses B2 and E2 (see sections 177 and 188 of the Act).

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#) [Download this resource \(PDF, 87KB\)](#)

{{ linkText }}

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

2008/024: Refusal to issue a code compliance certificate for a new house due to a dispute over compliance of jamb flashing

This document is not CITED BY any other resources:

Back

2008/024: Refusal to issue a code compliance certificate for a new house due to a dispute over compliance of jamb flashing

Show what documents this resource is CITED BY

Show what documents this resource CITES

Description

This determination arises from the decision of the territorial authority to refuse to issue a code compliance certificate for a new house because it was not satisfied that it complied with Clauses B2 'Durability' and E2 'External Moisture of the Building Code. The matter for determination is whether the jamb flashing system to the exterior joinery units as installed to the walls of the building comply with Clauses B2 and E2 (see sections 177 and 188 of the Act).

[View on Information Provider website](#) [Download this resource \(PDF, 87KB\)](#)

[2008/024: Refusal to issue a code compliance certificate for a new house due to a dispute over compliance of jamb flashing](#)

Description

This determination arises from the decision of the territorial authority to refuse to issue a code compliance certificate for a new house because it was not satisfied that it complied with Clauses B2 'Durability' and E2 'External Moisture of the Building Code. The matter for determination is whether the jamb flashing system to the exterior joinery units as installed to the walls of the building comply with Clauses B2 and E2 (see sections 177 and 188 of the Act).

[View on Information Provider website](#) [Download this resource \(PDF, 87KB\)](#)

This resource does not cite any other resources.

2008/024: Refusal to issue a code compliance certificate for a new house due to a dispute over compliance of jamb flashing

This resource does not CITE any other resources.

Back

Close

Table of Contents

Print

[Save](#)

Email

[Feedback](#)

<input type="text"/>	<input type="text"/>	<input type="text"/>
----------------------	----------------------	----------------------

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

<input type="text"/>	<input type="text"/>	<input type="text"/>
----------------------	----------------------	----------------------

[Feedback](#)