

Menu

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

Print

[Save](#)

Email

[Resource detail](#)

[Citations](#)

2008/073: Decision to refuse to issue a code compliance certificate due to concerns about the durability of macrocarpa lintels to a rammed earth house

[View on Information Provider website](#) [Download this resource \(PDF, 147KB\)](#)

{{ linkText }}

Abbreviation

2008/073

Valid from

05/08/2008

Information provider

Ministry of Business, Innovation and Employment

Information type

Determination

Format

PDF

Description

The matter for determination is whether the authority was correct in its decision to refuse to issue a code compliance certificate for a 5-year-old house because it was not satisfied that the exterior lintel beams comply with Clause B2 Durability of the Building Code.

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#) [Download this resource \(PDF, 147KB\)](#)

{{ linkText }}

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

2008/073: Decision to refuse to issue a code compliance certificate due to concerns about the durability of macrocarpa lintels to a rammed earth house

This document is not CITED BY any other resources:

Back

2008/073: Decision to refuse to issue a code compliance certificate due to concerns about the durability of macrocarpa lintels to a rammed earth house

Show what documents this resource is CITED BY

Show what documents this resource CITES

Description

The matter for determination is whether the authority was correct in its decision to refuse to issue a code compliance certificate for a 5-year-old house because it was not satisfied that the exterior lintel beams comply with Clause B2 Durability of the Building Code.

[View on Information Provider website](#) [Download this resource \(PDF, 147KB\)](#)

[2008/073: Decision to refuse to issue a code compliance certificate due to concerns about the durability of macrocarpa lintels to a rammed earth house](#)

Description

The matter for determination is whether the authority was correct in its decision to refuse to issue a code compliance certificate for a 5-year-old house because it was not satisfied that the exterior lintel beams comply with Clause B2 Durability of the Building Code.

[View on Information Provider website](#) [Download this resource \(PDF, 147KB\)](#)

This resource does not cite any other resources.

2008/073: Decision to refuse to issue a code compliance certificate due to concerns about the durability of macrocarpa lintels to a rammed earth house

This resource does not CITE any other resources.

Back

Close

Table of Contents

Print

[Save](#)

Email

[Feedback](#)

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

[Feedback](#)