Skip to main content Skip to primary navigation
Menu
<ul><li>Home Home</li><li>About this portal</li></ul>
·
<ul> <li><u>Latest updates</u></li> </ul>
Print Save Email
Resource detail

### 2010/063: Refusal to issue a code compliance certificate for a 9 year-old garage/sleepout

<u>View on Information Provider website Download this resource (PDF, 0KB)</u> {{ linkText }}

Abbreviation

2010/063

Valid from

16/07/2010

Information provider

Ministry of Business, Innovation and Employment

Author

Ministry of Business, Innovation and Employment

Information type

Determination

**Format** 

**PDF** 

### Description

This determination arose from the decision of the authority to refuse to issue a code compliance certificate for an 8-year-old outbuilding because it was not satisfied that it complied with certain clauses of the Building Code.

The matter determined was whether the authority was correct to refuse to issue a code compliance certificate.

It was be considered:

1. Whether the external cladding to the garage/sleepout complied with Clauses B2 Durability and E2 External Moisture;

- 2. Whether the sleepout bathroom complied with Clause E3 Internal Moisture;
- 3. Whether the elements that make up the building work complied with Clause B2 Durability, taking into account the age of the building.

For assistance with locating previous versions, please contact the information provider.

<u>View on Information Provider website Download this resource (PDF, 0KB)</u> {{ linkText }}

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

## 2010/063: Refusal to issue a code compliance certificate for a 9 year-old garage/sleepout

This document is not CITED BY any other resources:

Back

# 2010/063: Refusal to issue a code compliance certificate for a 9 year-old garage/sleepout

Show what documents this resource is CITED BY

Show what documents this resource CITES

#### Description

This determination arose from the decision of the authority to refuse to issue a code compliance certificate for an 8-year-old outbuilding because it was not satisfied that it complied with certain clauses of the Building Code.

The matter determined was whether the authority was correct to refuse to issue a code compliance certificate.

It was be considered:

- 1. Whether the external cladding to the garage/sleepout complied with Clauses B2 Durability and E2 External Moisture;
- 2. Whether the sleepout bathroom complied with Clause E3 Internal Moisture;
- 3. Whether the elements that make up the building work complied with Clause B2 Durability, taking into account the age of the building.

View on Information Provider website Download this resource (PDF, 0KB)

2010/063: Refusal to issue a code compliance certificate for a 9 year-old garage/sleepout

#### Description

This determination arose from the decision of the authority to refuse to issue a code compliance certificate for an 8-year-old outbuilding because it was not satisfied that it complied with certain clauses of the Building Code.

The matter determined was whether the authority was correct to refuse to issue a code compliance certificate.

It was be considered:

- 1. Whether the external cladding to the garage/sleepout complied with Clauses B2 Durability and E2 External Moisture;
- 2. Whether the sleepout bathroom complied with Clause E3 Internal Moisture;
- 3. Whether the elements that make up the building work complied with Clause B2 Durability, taking into account the age of the building.

View on Information Provider website Download this resource (PDF, 0KB)

This resource does not cite any other resources.

This resource does not CITE any other resources.

# 2010/063: Refusal to issue a code compliance certificate for a 9 year-old garage/sleepout

Back	
Close	
Table of Contents	
Print Save Email	
Feedback	
	 _
<ul> <li>Contact us</li> </ul>	
<ul> <li>Privacy policy</li> </ul>	
• <u>Disclaimer</u>	
<ul> <li>Copyright</li> </ul>	
	 _
<u>Feedback</u>	