

Menu

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

Print

[Save](#)

Email

[Resource detail](#)

[Citations](#)

2011/026: Refusal to issue a code compliance certificate due to the lack of inspections or a producer statement for shower waterproofing in a house

[View on Information Provider website](#) [Download this resource \(PDF, 74KB\)](#)

{{ linkText }}

Abbreviation

2011/026

Valid from

01/04/2011

Information provider

Ministry of Business, Innovation and Employment

Information type

Determination

Format

PDF

Description

This determination arises from the authority's decision to refuse to issue a code compliance certificate for a new house, because it is not satisfied that the waterproofing to the showers complies with certain clauses of the Building Code. The matter to be determined is whether the authority's decision not to issue a code compliance certificate was correct. In determining this it must be considered whether the building work in question complies with Clauses E3 Internal moisture and B2 Durability of the Building Code.

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#) [Download this resource \(PDF, 74KB\)](#)

{{ linkText }}

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

2011/026: Refusal to issue a code compliance certificate due to the lack of inspections or a producer statement for shower waterproofing in a house

This document is not CITED BY any other resources:

Back

2011/026: Refusal to issue a code compliance certificate due to the lack of inspections or a producer statement for shower waterproofing in a house

Show what documents this resource is CITED BY

Show what documents this resource CITES

Description

This determination arises from the authority's decision to refuse to issue a code compliance certificate for a new house, because it is not satisfied that the waterproofing to the showers complies with certain clauses of the Building Code. The matter to be determined is whether the authority's decision not to issue a code compliance certificate was correct. In determining this it must be considered whether the building work in question complies with Clauses E3 Internal moisture and B2 Durability of the Building Code.

[View on Information Provider website](#) [Download this resource \(PDF, 74KB\)](#)

[2011/026: Refusal to issue a code compliance certificate due to the lack of inspections or a producer statement for shower waterproofing in a house](#)

Description

This determination arises from the authority's decision to refuse to issue a code compliance certificate for a new house, because it is not satisfied that the waterproofing to the showers complies with certain clauses of the Building Code. The matter to be determined is whether the authority's decision not to issue a code compliance certificate was correct. In determining this it must be considered whether the building work in question complies with Clauses E3 Internal moisture and B2 Durability of the Building Code.

[View on Information Provider website](#) [Download this resource \(PDF, 74KB\)](#)

This resource does not cite any other resources.

This resource does not cite any other resources.

2011/026: Refusal to issue a code compliance certificate due to the lack of inspections or a producer statement for shower waterproofing in a house

This resource does not CITE any other resources.

Back

Close

Table of Contents

Print

[Save](#)

Email

[Feedback](#)

<input type="text"/>	<input type="text"/>	<input type="text"/>
----------------------	----------------------	----------------------

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

<input type="text"/>	<input type="text"/>	<input type="text"/>
----------------------	----------------------	----------------------

[Feedback](#)