

Menu

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

Print [Save](#) Email

[Resource detail](#)

[Citations](#)

2011/064: Regarding the refusal to issue a code compliance certificate for a 16 year-old house with ply and batten cladding

[View on Information Provider website](#) [Download this resource \(PDF, 84KB\)](#)

Abbreviation

2011/064

Valid from

27/06/2011

Information provider

Ministry of Business, Innovation and Employment

Information type

Determination

Format

PDF

Description

Regarding the refusal to issue a code compliance certificate for a 16-year-old house with ply and batten cladding at 3 Mayroyd Terrace, Nelson

Scope

This determination arose from the decision of the authority to refuse to issue a code compliance certificate for a 16-year-old house because it was not satisfied that the house complied with certain clauses of the Building Code (First Schedule, Building Regulations 1992).

The matter to be determined was whether the authority was correct to refuse to issue a code compliance certificate.

In deciding this, the following was considered:

- Whether the external envelope to the house (the external envelope) complied with Clause B2 Durability and Clause E2 External Moisture of the Building Code;
- Whether the elements that make up the building work complied with Building Code Clause B2 Durability, taking into account the age of the house.

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#) [Download this resource \(PDF, 84KB\)](#)

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

2011/064: Regarding the refusal to issue a code compliance certificate for a 16 year-old house with ply and batten cladding

This document is not CITED BY any other resources:

2011/064: Regarding the refusal to issue a code compliance certificate for a 16 year-old house with ply and batten cladding

Description

Regarding the refusal to issue a code compliance certificate for a 16-year-old house with ply and batten cladding at 3 Mayroyd Terrace, Nelson

[View on Information Provider website](#) [Download this resource \(PDF, 84KB\)](#)

[2011/064: Regarding the refusal to issue a code compliance certificate for a 16 year-old house with ply and batten cladding](#)

Description

Regarding the refusal to issue a code compliance certificate for a 16-year-old house with ply and

batten cladding at 3 Mayroyd Terrace, Nelson

[View on Information Provider website](#) [Download this resource \(PDF, 84KB\)](#)

This resource does not cite any other resources.

2011/064: Regarding the refusal to issue a code compliance certificate for a 16 year-old house with ply and batten cladding

This resource does not CITE any other resources.

Back

Close

Table of Contents

Print

[Save](#)

Email

[Feedback](#)

<input type="text"/>	<input type="text"/>	<input type="text"/>
----------------------	----------------------	----------------------

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

<input type="text"/>	<input type="text"/>	<input type="text"/>
----------------------	----------------------	----------------------

[Feedback](#)