

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

[Save](#)

[Resource detail](#)
[Citations](#)

2014/052: Regarding the authoritys exercise of powers in issuing a notice to fix for a pellet burner installed in an existing chimney for a house

[View on Information Provider website](#) [Download this resource \(PDF, 95KB\)](#)

Abbreviation

2014/052

Valid from

21/10/2014

Information provider

Ministry of Business, Innovation and Employment

Information type

Determination

Format

PDF

Description

This determination arises from the installation of a wood pellet burner into an existing brick chimney. The owners obtained a building consent for the installation.

The authority is currently refusing to issue a code compliance certificate and issued a notice to fix to the owners which stated the required testing of the pellet burner had not been completed where the timber wood is in contact with the chimney.

The matter to be determined is therefore whether the authority correctly exercised its powers of decision in issuing a notice to fix for the installation of a pellet burner.

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#) [Download this resource \(PDF, 95KB\)](#)

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

2014/052: Regarding the authoritys exercise of powers in issuing a notice to fix for a pellet burner installed in an existing chimney for a house

This document is not CITED BY any other resources:

2014/052: Regarding the authoritys exercise of powers in issuing a notice to fix for a pellet burner installed in an existing chimney for a house

Show what documents this resource is CITED BY

Show what documents this resource CITES

Description

This determination arises from the installation of a wood pellet burner into an existing brick chimney. The owners obtained a building consent for the installation.

The authority is currently refusing to issue a code compliance certificate and issued a notice to fix to the owners which stated the required testing of the pellet burner had not been completed where the timber wood is in contact with the chimney.

The matter to be determined is therefore whether the authority correctly exercised its powers of decision in issuing a notice to fix for the installation of a pellet burner.

[View on Information Provider website](#) [Download this resource \(PDF, 95KB\)](#)

[2014/052: Regarding the authoritys exercise of powers in issuing a notice to fix for a pellet burner installed in an existing chimney for a house](#)

Description

This determination arises from the installation of a wood pellet burner into an existing brick chimney. The owners obtained a building consent for the installation.

The authority is currently refusing to issue a code compliance certificate and issued a notice to fix to the owners which stated the required testing of the pellet burner had not been completed where the timber wood is in contact with the chimney.

The matter to be determined is therefore whether the authority correctly exercised its powers of decision in issuing a notice to fix for the installation of a pellet burner.

[View on Information Provider website](#) [Download this resource \(PDF, 95KB\)](#)

This resource does not cite any other resources.

2014/052: Regarding the authoritys exercise of powers in issuing a notice to fix for a pellet burner installed in an existing chimney for a house

This resource does not CITE any other resources.

Back

Close

Table of Contents

Print [Save](#) Email

Feedback

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

