

Menu

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

Print

[Save](#)

Email

[Resource detail](#)

[Citations](#)

## 2017/018: Refusal to issue a code compliance certificate for a 10-year-old house with plywood, stone veneer and horizontal weatherboards

[View on Information Provider website](#) [Download this resource \(PDF, 187KB\)](#)

{{ linkText }}

Abbreviation

2017/018

Valid from

15/03/2017

---

Information provider

Ministry of Business, Innovation and Employment

Information type

Determination

Format

PDF

---

Description

This determination concerned the compliance of a 10-year-old house with plywood, stone veneer, and horizontal weatherboard cladding.

This determination considered the authority's reasons for refusing to issue the code compliance certificate, and whether the house complied with the requirements of the Building Code.

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#) [Download this resource \(PDF, 187KB\)](#)

{{ linkText }}

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

## **2017/018: Refusal to issue a code compliance certificate for a 10-year-old house with plywood, stone veneer and horizontal weatherboards**

This document is not CITED BY any other resources:

Back

## **2017/018: Refusal to issue a code compliance certificate for a 10-year-old house with plywood, stone veneer and horizontal weatherboards**

Show what documents this resource is CITED BY

Show what documents this resource CITES

### **Description**

This determination concerned the compliance of a 10-year-old house with plywood, stone veneer, and horizontal weatherboard cladding.

This determination considered the authority's reasons for refusing to issue the code compliance certificate, and whether the house complied with the requirements of the Building Code.

[View on Information Provider website](#) [Download this resource \(PDF, 187KB\)](#)

[2017/018: Refusal to issue a code compliance certificate for a 10-year-old house with plywood, stone veneer and horizontal weatherboards](#)

### **Description**

This determination concerned the compliance of a 10-year-old house with plywood, stone veneer, and horizontal weatherboard cladding.

This determination considered the authority's reasons for refusing to issue the code compliance certificate, and whether the house complied with the requirements of the Building Code.

[View on Information Provider website](#) [Download this resource \(PDF, 187KB\)](#)

This resource does not cite any other resources.

# 2017/018: Refusal to issue a code compliance certificate for a 10-year-old house with plywood, stone veneer and horizontal weatherboards

This resource does not CITE any other resources.

Back

Close

## Table of Contents

Print

[Save](#)

Email

[Feedback](#)

<input type="text"/>	<input type="text"/>	<input type="text"/>
----------------------	----------------------	----------------------

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

<input type="text"/>	<input type="text"/>	<input type="text"/>
----------------------	----------------------	----------------------

[Feedback](#)