

- [Home Home](#)
- [About this portal](#)
- [Latest updates](#)

[Resource detail](#)
[Citations](#)

AS 2888.4-1986 Methods of testing plastics waste fittings - Method 4: Method for air pressure/vacuum testing of plastics waste fittings

[View on Information Provider website](#)

Abbreviation

AS 2888.4-1986

Valid from

07/07/1986

Information provider

SAI Global

Author

Standards Australia

Information type

Australian Standard

Format

Hard copy, PDF

Cited By

[This resource is cited by 1 document \(show Citations\)](#)

Description

This standard sets out the method for determining the resistance of plastics waste fittings to the application of internal air pressure followed by a vacuum.

For assistance with locating previous versions, please contact the information provider.

[View on Information Provider website](#)

For assistance with locating previous versions, please contact the information provider.

This resource is cited by:

AS 2888.4-1986 Methods of testing plastics waste fittings - Method 4: Method for air pressure/vacuum testing of plastics waste fittings

This document is CITED BY:

- [AS 2887-1993](#)

AS 2888.4-1986 is cited by AS 2887-1993 (R2017) Plastic waste fittings

Back

AS 2888.4-1986 Methods of testing plastics waste fittings - Method 4: Method for air pressure/vacuum testing of plastics waste fittings

Show what documents this resource is CITED BY

Show what documents this resource CITES

Description

This standard sets out the method for determining the resistance of plastics waste fittings to the application of internal air pressure followed by a vacuum.

[View on Information Provider website](#)

[AS 2888.4-1986 Methods of testing plastics waste fittings - Method 4: Method for air pressure/vacuum testing of plastics waste fittings](#)

Description

This standard sets out the method for determining the resistance of plastics waste fittings to the application of internal air pressure followed by a vacuum.

[View on Information Provider website](#)

This resource does not cite any other resources.

AS 2888.4-1986 Methods of testing plastics waste fittings - Method 4: Method for air pressure/vacuum testing of plastics waste fittings

This resource does not CITE any other resources.

Back

Close

Table of Contents

Print [Save](#) Email

Feedback

- [Contact us](#)
- [Privacy policy](#)
- [Disclaimer](#)
- [Copyright](#)

Feedback