Skip to main content Skip to prin	mary navigation
 Home Home About this portal Latest updates	
Print Save Email	

Brick veneer and mortar strength in earthquakes

View on Information Provider website

Valid from
01/06/2013

Information provider
Ministry of Business, Innovation and Employment
Information type
Section 175 guidance
Format
Website

Description

Citations

Modern clay brick veneer construction on timber framed and steel framed houses generally performed well during the Canterbury earthquakes. BRANZ simulated: design level earthquake displacements of a two storey, brick veneer, timber framed building and shake tests and racking tests of single storey buildings. These tests indicated that modern construction details performed well in design level earthquake simulations.

For assistance with locating previous versions, please contact the information provider.

<u>View on Information Provider website</u> {{ linkText }}

For assistance with locating previous versions, please contact the information provider.

This resource is not cited by any other resources.

Brick veneer and mortar strength in earthquakes

This document is not CITED BY any other resources:

Back

Brick veneer and mortar strength in earthquakes

Show what documents this resource is CITED BY

Show what documents this resource CITES

Description

Modern clay brick veneer construction on timber framed and steel framed houses generally performed well during the Canterbury earthquakes. BRANZ simulated: design level earthquake displacements of a two storey, brick veneer, timber framed building and shake tests and racking tests of single storey buildings. These tests indicated that modern construction details performed well in design level earthquake simulations.

View on Information Provider website

Brick veneer and mortar strength in earthquakes

Description

Modern clay brick veneer construction on timber framed and steel framed houses generally performed well during the Canterbury earthquakes. BRANZ simulated: design level earthquake displacements of a two storey, brick veneer, timber framed building and shake tests and racking tests of single storey buildings. These tests indicated that modern construction details performed well in design level earthquake simulations.

View on Information Provider website

This resource does not cite any other resources.

Brick veneer and mortar strength in earthquakes

This resource does not CITE any other resources.

Back

Close

Table of Contents

Print Save Email		
Feedback		
• Contact us		
 Privacy policy 		
• <u>Disclaimer</u>		
 Copyright 		
		<u> </u>

<u>Feedback</u>